

SPACEK s.r.o. , Lesní 25, 695 01 Hodonín, Czech republic

THE SD-1 ACCIDENT REPORT

The SD-1 TD registration N123SD was crashed in Spanish Fork Airport, Utah, USA on September 6, 2013. The pilot recieved fatal injuries.

In accordance to witnesses performed pilot low altitude aerobatics with consequent loss of control over airplane.

We warn all present and future pilots from performing of any aerobatic maneuvres onboard of SD-1.

A handwritten signature in blue ink, appearing to read 'Igor Spacek', is positioned above the printed name and title.

Igor Spacek
Managing director